

Chainsaw Sheath

Installation Instructions on Wallenstein Skidding Winch



Holes are drilled on the back side of the winch.



Loosen the (3) bottom bolts on the Chainsaw Sheath



Attach to the Skidding Winch

